



2 Use MCV (45° Vee shape cutter). Cut on centre line of offset line with 1mm offset towards geometry line. Cut 16mm deep in 2 passes recognising amount of material to be machined . Last cut is 5mm. Replacement blade(MCVB).